

Monthly Hose	Inspection	Location
Submitted By	Cayden Gray	Tay
Surrogate	Cayden Gray	Time Midland
Started On	February 1 2024, 12:41pm	
Submitted On	February 1 2024, 2:39pm (2 hours)	West Odessa Odessa
Weather	72°, clear	Arcade (14) Google Map data ©2024
Version	V1 (latest)	
Updated	February 1 2024, 2:39pm	
Report No.	36230470	

Monthly Hose Inspection

CAR	RIER	
Date/Time		February 1st 2024 2:38 PM
TRA	ILER INFORMATION	
Prover No.		PROVER_4
# o	f Hoses	2
	Inspection Step 1	Satisfactory
	Inspection Step 2	Satisfactory
	Inspection Step 3	Satisfactory
	Inspection Step 4	Satisfactory
1	Inspection Step 5	Satisfactory
	Inspection Step 6	Satisfactory
	Inspection Step 7	Satisfactory
	Inspection Step 8	Satisfactory
	Serial Number	<u>CHTX-29788</u>

	Inspection Step 1	Satisfactory
	Inspection Step 2	Satisfactory
	Inspection Step 3	Satisfactory
	Inspection Step 4	Satisfactory
2	Inspection Step 5	Satisfactory
	Inspection Step 6	Satisfactory
	Inspection Step 7	Satisfactory
	Inspection Step 8	Satisfactory
	Serial Number	<u>CHTX-29787</u>

INSPECTION REMARKS / SIGNATURES

Driver's Signature

Generated Thursday, February 1st 2024, 2:52pm CST

